### PROGRESSIVE COMMERCIAL AQUATICS

A LANDMARK AQUATIC COMPANY


#### City of Jersey Village

Date: 1/8/2024LAP POOL

General Observations:

Tile/Coping: There are numerous areas where tile is popping off and coping is either broken and/or not attached to deck. Broken coping and moving coping can be a tripping hazard. There appears to be a significant amount of movement around the pool, decking is cracking as well.

Quote for replacing tile and coping \$ 39, 675.00\*Please note that is there is major ground/earth movement occurring this could remain an on going problem.





- Plaster: Plaster is in ok to poor condition. There is pitting scattered throughout the pool. There are areas where plaster is falling off corners specifically. There is a significant crack in the deep end and pop ups that expose the concrete shell. Per operators, the pool is constantly having to be filled, even in off season. This is indictive of a leak. PCA highly recommends having leak detection done. Per code XXXXXXXX
  - Quote for new quartz plaster \$106, 400.00
  - Estimate for leak detection \$3000-5000. Can get an official quote is requested.
  - There are also broken steps present that need to be fix before any patrons enter the water. This is a safety issue.



## PROGRESSIVE COMMERCIAL AQUATICS

A LANDMARK AQUATIC COMPANY

#### BABY POOL

- General Observations:
  - Tile/Coping: There are numerous areas where tile is popping off and coping is either broken and/or not attached to deck. Broken coping and moving coping can be a tripping hazard. There appears to be a significant amount of movement around the pool, decking is cracking as well. Quote to replace is included in Lap Pool tile/coping quote above.
  - Chemical Feed System: There is currently NO automatic chemical controller. This is not best practice. Per code XXXXXXXXXXXXXX. Quote for automatic chemical controller \$5000\*electrical not included. New chemical system will also need to be installed, at a minimum stenner pumps will be need for chlorine and acid, \$800\*electrical not included.
  - Chemicals & General Pump area: The pump area is not gated or secured. This is not best practice. Chemical feed system and chemicals may also be in this area. This should be gated so that no patrons can gain access.
  - Backwash: Per operators, the backwash line for the baby pool system drain into flood, not sewer. This is not to code. Backwash water should be directed to sewer and be treated like waste. The cost to bring this to code is unknown. Sewer would have to be located, and a plumber to provide cost.

## PROGRESSIVE COMMERCIAL AQUATICS

A LANDMARK AQUATIC COMPANY

- LAP POOL PUMP HOUSE
  - o General Observations:
    - Turnover Rates:
      - Pool volume: 250,000 gallons
      - Pump suction –6" Schedule 80 PVC Pipe Maximum allowable flow at 6 Ft/ Sec 487
         GPM
      - Filtered return -4" Schedule 80 PVC Pipe Maximum allow flow at 10 Ft/Sec -358 GPM
      - Current Filtration (2) Water Co. SMF1400 55′ Each filter has 7 Ft² of filtration or 21 Ft² Total
      - Current pump Pentair EQ 7.5 HP
      - Flow rate on flow meter = 300 GPM (observed)
        - o PRE-1999 CONSTRUCTION (Facility Qualifies):
          - 250,000 gal /8 hr turnover = 31,250 gallons per hour (Max 8 hour turnover)
          - 31,250 gph /60 min = 520 gpm minimum allowable flow rate for PRE-1999 Pools
          - 15 gpm/sq ft x 21 sq ft = 315 gpm (Recommended filtration rate)
          - 20 gpm/sq ft x 21 sq ft = 420 gpm (Max allowed filtration rate per NSF Listing)
        - o POST-1999 CONSTRUCTION
          - 250,000 gal /6 hr = 41,666 gallons per hour (Max 6 hour turnover)
          - 41,666 gph/60 min = 694 GPM
          - 15 gpm/sq ft x 21 sq ft = 315 gpm (Recommended filtration rate)
          - 20 gpm/sq ft x 21 sq ft = 420 gpm (Max allowed filtration rate per NSF Listing)
    - Chemical Venting: Upon entry the chemical fumes were extremely overwhelming. This is not but practice and may be harmful to operators. Outside of being harmful to operators, the corrosiveness of muriatic acid is extremely harmful to the build and equipment. You can see from the photos below that the fumes are attacking every metal surface. Items being visibly affected:
      - Main power entering pump house the main conduit is being extremely corroded. This
        may start to cause electrical issues.
      - Bolts/supports every bolt and metal support on pool pump equipment is heavily corroded this will eventually lead to issues/effect the integrity of the bolts and supports.
      - VFD, Controllers & Flow Meter The VFD has extensive corrosion. The fumes are most likely attacking all the electronic parts with in the controller as well. The flow meter is not operational, it is believed that the connection wire has corroded out. Further investigation is required to see if flow meter itself is also affected by corrosion. A flow meter is required by Texas code. Venting of acid fumes could lead to thousands of dollars of damage.

# PROGRESSIVE COMMERCIAL AQUATICS

A LANDMARK AQUATIC COMPANY



- MISC
  - o Ensure that entrance building, and bath house is ADA compliant.
  - o Ensure that all chemicals are stored where patrons do not have access to them.

Erica Peace Director of Sales

2510 Farrell Rd Houston, TX 77073

281-982-0212



#### **Invoice**

Invoice #: 128760 Date: 3/26/2024

**Shipping Method:** 

Salesperson: carlos Sales Order #: S29218

Customer PO #:

**Bill To** City of Jersey Village (JERSEY)

Isaac Rincons 16501 Jersey Drive irecinos@jerseyvillagetx.com

Jersey Village, TX 77040

**Ship To** City of Jersey Village (JERSEY)

Isaac Rincons 16501 Jersey Drive

irecinos@jerseyvillagetx.com Jersey Village, TX 77040

**Phone** 713-466-2102

Tax Group 005

Item	Description	Qty	UOM	Unit Price	Tax	Total
NONSTOCK	In Wall Steps	3	EA	\$70.00	\$0.00	\$210.00
LABOR	Labor to remove old Steps & Install new steps	1	EA EA	\$70.00 \$1,000.00	\$0.00 \$0.00	\$210.00 \$1,000.00

EXMPT \$0.00

Total \$1,210.00
Tax Total \$0.00
Grand Total \$1,210.00

There will be a 25% restocking fee on all returned items. Credit Card Purchases will include a 2% Service Fee Due to Material Shortages, Quotes are only valid for 60 days

2510 Farrell Rd Houston, TX 77073

281-982-0212



### Invoice

Invoice #: 128380 Date: 12/15/2023

Shipping Method:

Salesperson: carlos Sales Order #: S28677

Customer PO #:

Bill To City of Jersey Village (JERSEY)

Isaac Rincons 16501 Jersey Drive irecinos@jerseyvillagetx.com

Jersey Village, TX 77040

01-39-4007

Ship To City of Jersey Village (JERSEY)

Isaac Rincons 16501 Jersey Drive

irecinos@jerseyvillagetx.com Jersey Village, TX 77040

Phone 713-466-2102

Tax Group 005

Item	Description	Qty	UOM	Unit Price	Tax	Total
NONSTOCK	Stainless Steel unistrut supports	1	EA	\$1,500.00	\$0.00	\$1,500.00
LABOR	Labor for Service Jobs	1	EA	\$650.00	\$0.00	\$650.00

EXMPT \$0.00

Total \$2,150.00
Tax Total \$0.00
Grand Total \$2,150.00

There will be a 25% restocking fee on all returned items. Credit Card Purchases will include a 2% Service Fee Due to Material Shortages, Quotes are only valid for 60 days

2510 Farrell Rd Houston, TX 77073

281-982-0212



#### Invoice

Invoice #: 125208 1/31/2022 Date:

Shipping Method:

Salesperson: carlos Sales Order #: S25239

Customer PO#:

Bill To City of Jersey Village (JERSEY)

> Josh Rodrigue 16501 Jersey Drive jrodrigue@jerseyvillagetx.com

Jersey Village, TX 77040

Ship To

City of Jersey Village (JERSEY)

Josh Rodrigue 16501 Jersey Drive

jrodrigue@jerseyvillagetx.com

Jersey Village, TX 77040

Phone 713-466-2102

Tax Group 005 Asaac Recinos

01-39-4007

Item	Description	Qty	UOM	Unit Price	Tax	Total
NONSTOCK	4" Waterco Filter Bulkhead	2	EA	\$355.00	\$0.00	\$710.00
SAND 50#	Filter sand 50# bag	106	EA	\$14.50	\$0.00	\$1,537.00
GRAVEL 50#	Gravel for filter 50# bag	15	EA	\$14.50	\$0.00	\$217.50
LABOR	Labor for Service Jobs	1	EA	\$2,600.00	\$0.00	\$2,600.00
NONSTOCK	Old Media Haul Off	1	EA	\$350.00	\$0.00	\$350.00
GRAVEL 50#	Gravel for filter 50# bag	35	EA	\$0.00	\$0.00	\$0.00
NONSTOCK	Lateral	3	EA	\$45.00	\$0.00	\$135.00

**EXMPT** \$0.00

> Total \$5,549.50 Tax Total \$0.00 **Grand Total** \$5,549.50

2510 Farrell Rd Houston, TX 77073

281-982-0212



#### Invoice

Invoice #: 128219 Date: 11/3/2023

Shipping Method:

Salesperson: carlos Sales Order #: S28280

Customer PO #:

Bill To City of Jersey Village (JERSEY)

Isaac Rincons 16501 Jersey Drive irecinos@jerseyvillagetx.com

Jersey Village, TX 77040

Ship To

City of Jersey Village (JERSEY)

Isaac Rincons 16501 Jersey Drive

irecinos@jerseyvillagetx.com Jersey Village, TX 77040

Asaac Recinos

Phone

713-466-2102

01-39-4007

Tax Group 005

Item	Description	Qty	UOM	Unit Price	Tax	Total
NONSTOCK	4" Bulkhead (12221000A)	1	EA	\$125.00	\$0.00	\$125.00
NONSTOCK	4"-6" PVC Parts & Materials	1	EA	\$450.00	\$0.00	\$450.00
LABOR	Labor for Service Jobs	1	EA	\$975.00	\$0.00	\$975.00
FREIGHT	Freight charges	1	EA	\$45.00	\$0.00	\$45.00

EXMPT \$0.00

Total \$1,595.00
Tax Total \$0.00
Grand Total \$1,595.00

There will be a 25% restocking fee on all returned items. Credit Card Purchases will include a 2% Service Fee Due to Material Shortages, Quotes are only valid for 60 days

2510 Farrell Rd Houston, TX 77073

281-982-0212



#### Invoice

Invoice #: 128219 Date: 11/3/2023

Shipping Method:

Salesperson: carlos Sales Order #: S28280

Customer PO #:

Bill To City of Jersey Village (JERSEY)

Isaac Rincons 16501 Jersey Drive irecinos@jerseyvillagetx.com Jersey Village, TX 77040 Ship To City of Jersey Village (JERSEY)

Isaac Rincons 16501 Jersey Drive

irecinos@jerseyvillagetx.com Jersey Village, TX 77040

Phone 713-466-2102

Tax Group 005

Item	Description	Qty	UOM	Unit Price	Tax	Total
4"x6" Ruducer (1) 6" 90* (1) 6" Flange (1) 6" Coupling (1) 6" Tee (1) Glue & Primer (1qt Ea)						

EXMPT \$0.00

Total \$1,595.00
Tax Total \$0.00
Grand Total \$1,595.00

There will be a 25% restocking fee on all returned items. Credit Card Purchases will include a 2% Service Fee Due to Material Shortages, Quotes are only valid for 60 days

2510 Farrell Rd Houston, TX 77073

281-982-0212



### Invoice

Invoice #: 127017 Date: 2/24/2023

Shipping Method:

Salesperson: carlos Sales Order #: S27227

Customer PO #:

Bill To City of Jersey Village (JERSEY)

Isaac Rincons 16501 Jersey Drive irecinos@jerseyvillagetx.com

Jersey Village, TX 77040

Ship To City of Jersey Village (JERSEY)

Isaac Rincons 16501 Jersey Drive

irecinos@jerseyvillagetx.com Jersey Village, TX 77040

Phone 713-466-2102

Tax Group 005

Item	Description	Qty	UOM	Unit Price	Tax	Total
NONSTOCK	Lateral Kit (SMD1400-LAT4)	1	EA	\$325.00	\$0.00	\$325.00
SAND 50#	Filter sand 50# bag	106	EA	\$14.50	\$0.00	\$1,537.00
GRAVEL 50#	Gravel for filter 50# bag	10	EA	\$14.50	\$0.00	\$145.00
LABOR	Labor for Service Jobs	1	EA	\$3,200.00	\$0.00	\$3,200.00
NONSTOCK	Old Media Haul Off	1	EA	\$500.00	\$0.00	\$500.00

EXMPT \$0.00

Total \$5,707.00
Tax Total \$0.00
Grand Total \$5,707.00

There will be a 25% restocking fee on all returned items. Credit Card Purchases will include a 2% Service Fee Due to Material Shortages, Quotes are only valid for 60 days

2510 Farrell Rd Houston, TX 77073

281-982-0212



#### Invoice

Invoice #: 128640 Date: 3/1/2024

Shipping Method:

Salesperson: carlos Sales Order #: S29062

Customer PO #:

Bill To City of Jersey Village (JERSEY)

Isaac Rincons
16501 Jersey Drive

irecinos@jerseyvillagetx.com Jersey Village, TX 77040

01-39-4007

Ship To City of Jersey Village (JERSEY)

Isaac Rincons 16501 Jersey Drive

irecinos@jerseyvillagetx.com Jersey Village, TX 77040

Phone 713-466-2102

Tax Group 005



Item	Description	Qty	UOM	Unit Price	Tax	Total
NONSTOCK	PVC Parts & Materials	1	EA	\$225.00	\$0.00	\$225.00
LABOR	Labor for Service Jobs	1	EA	\$275.00	\$0.00	\$275.00

EXMPT \$0.00

 Total
 \$500.00

 Tax Total
 \$0.00

 Grand Total
 \$500.00

There will be a 25% restocking fee on all returned items. Credit Card Purchases will include a 2% Service Fee Due to Material Shortages, Quotes are only valid for 60 days